

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

## REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

REPLY TO THE ATTENTION OF:

January 11, 2018

LU-16J

Mr. Lee K. Holder, P.E. Golder Associates, Inc. 18300 NE Union Hill Road, Suite 200 Redmond, Washington 98052

RE:

Self-Implementing Polychlorinated Biphenyls (PCB) Cleanup

Former Satralloy Site 4243 County Road 74

Mingo Junction, Ohio 43938

Dear Mr. Holder:

The U.S. Environmental Protection Agency has reviewed the December 14, 2017, report documenting the cleanup conducted pursuant to 40 CFR 761.61(a) at the above-referenced facility. Based on our review, the document requires revision to:

- 1. Include a map showing locations of the verification samples.
- 2. Include laboratory results from the verification sampling. This may be provided in electronic format.
- 3. Document the recording, in accordance with State law, a notation on the deed to the property, or on some other instrument which is normally examined during a title search, that will in perpetuity notify any potential purchaser of the property:
  - (a) That the land has been used for PCB remediation waste disposal and is restricted to use as a low occupancy area as defined in §761.3.
  - (b) The applicable cleanup levels left at the site, inside the fence, and/or under the cap.

Please revise the report to include the requested information and provide a revised report within 60 days of this letter. If you have any questions, please contact me by e-mail at ohl.tamara@epa.gov or by telephone at (312) 886-0991.

Sincerely,

Tamara Ohl

Project Manager

Tamarathe

Land and Chemicals Division

Cc: Maria Galanti, Ohio EPA